



1:35

Head Desktop Model



**Hi**  
RX-93

AE-E-FS-F

*Head Desktop Model*  
**νGUNDAM.**



### 【组装时注意】


- ◆ 组装前请详细阅读说明书。
- ◆ 请将零件按编号整齐组装，组装后把边角料丢弃。
- ◆ 零配件当中有带尖锐或刺手的，在组装时请小心。
- ◆ 建议在涂装粘贴时使用安全的“水性涂料”。

### 【NOTICE WHILE ASSEMBLING】

- ◆ Please read the instruction carefully before assembly.
- ◆ Please assemble the parts as per serial numbers and discard the leftover material after assembly.
- ◆ While assembling, please pay attention that some of the parts may be sharp-pointed or aciculate.
- ◆ Please use the safe "aqueous coating" while painting.

## 零件目录(PARTS LIST)


板件 A




板件 B




板件 C




板件 D




板件 J



板件 K




板件 E




### 套件附带配件：

- ① 标志水贴X1
- ② 动力金属管X5
- ③ 发光电路组件X1


板件 G




板件 I




板件 H



板件 F



板件 L











# 16 A14 ※该部位组装请与发光电路同时组装！




## 发光电路组装布线图




※该部位组装过程请按顺序进行！


# 17 A15



# 19 A17




# 18 A16







## 20 A18



## 21 A19




## 22 A20







# 23 B01




# 24 B02




# 25 B03




# 26 B04




# 27 B05




# 28 B06




# 29 B07




# 30 B08




# 31 B09




# 32 B10




# 33 B11



# 34 B12




# 35 B13







# 36 B14




# 37 B15




# 38 B16




# 39 B17



# 40 B18




# 41 B19




※该部位组装过程请按顺序进行!

# 42 B20




※该部位组装过程请按顺序进行!


# 43 B21




# 44 B22




# 45



# 46 B23




# 47 B24






47




48 B25







# 49 C01 X2(该过程需制作2组！)




# 50 C02 X2(该过程需制作2组！)




# 51 C03 X2(该过程需制作2组！)




# 52 C04 X2(该过程需制作2组！)



# 53 C05 X2(该过程需制作2组！)




# 54 C06 X3(该过程需制作3组！)




Scanned by www.plasticandplasters.com


# 55 C07




# 56 C08



# 57 C09




# 58 C10






## 59 C11




※该部位组装过程请按顺序进行！

## 60 组装完成




※该部位组装过程请同时将发光电路连接起来！






水贴指示范例

侧面指示范例



正面指示范例





*Head Desktop Model*  
**Hi-V GUNDAM.**  
RX-93

